

Return  
:

'\*' OK ready  
':' Enter a hex value  
'?x' Error

Error codes:

1 no Sensor found  
2 more then one Sensor  
3 bit error  
4 cheksum error

\*  
\*  
\*

Cooli V 2.0

\* hh  
Cooli V 2.0

Comand :

'U' Powersupply control Soft UART 9600 8+1 non  
'C' Power polarity 'H' Head 'C' Cool  
'A' set a new sensor address  
'G' read one sensor address  
'T' starts the measurement of the actuall Sensor  
'R' reads the last measurement  
'M' measure and read the Temperature of the aktuall sensor  
'B' DIGITAL I/O I INIT, W write Data to Outputs, R Read Data  
'D' DAC Output 16 bit (channel No. D15 D14 1 1 DAC Data D11 ... D0 )  
'V' ADC Input Select cannel 3 bit, Return (0 channel No. D14..D12  
'H' Print this list

Return:

'\*' OK ready  
':' Enter a hex value  
'?x' Error

Error codes:

1 no Sensor found  
2 more then one Sensor  
3 bit error  
4 cheksum error