

R1
1K
1N914
CR1
CR2
R2
U1
U2
U3
U4
U5
U6
U7
U8
U9
U10
U11
U12
U13
U14
U15
MAX395
J1
HDR 30-PIN R/A



LINK CARD CABLE
TEST BOARD

CABLTST.PCB

Wed Dec 23 1998

12. buy op-07s from storeroom

13. buy rubber feet from storeroom, add holes

7. add testpoints

8. add op07

9. add pullup/pulldown resistors w/jumpers

ok
10. delete "reset" and "v-" traces, vias, caps

ok
11. shrink board in

ok
1. move J3/J2 to top/bottom?

ok
2. U8, U9 pins 6,16 connected? no

ok
3. power supply connections? v- = dgnd

4. agnd and dgnd? add jumper

ok
5. reset pins to +5V? yes

14. check storeroom for max (rip w/dad) chips po'd by sam

15. check connectors for footprint