

UCSB Test Tail Parts

Updated: **2/24/2003**

ITEM	DESCRIPTION	VERSION	Part No.	Manufacturer	Cost	Note 8 Required	Ordered	Order Total \$	Stock	STV1.12 Prod. 1/23/2003
1	HV Tail Kapton Ckt	1.10	HVTAIL3.MAX	Channel	\$30.00	0	0	0	2	0
2	HV Tail Kapton Ckt	2.00	HVTAIL4.MAX	Cirexx	\$20.00	276	0	0	0	0
3	HV Tail Kapton Ckt	3.00	HVTAIL5.MAX	Cirexx	\$17.35	390	400	6940	30	0
4	16 cont header	HV-J3	AXN416330S	NAIS/Aromat	\$1.40	650	375	525	311	0
5	16 cont socket	HV-J4	AXN316038S	NAIS/Aromat	\$1.40	650	375	525	310	0
6	40 cont header	SIG-J2	AXN4400330S	NAIS/Aromat	\$2.21	650	375	829	272	31
7	40 cont socket	SIG-J1	AXN340038S	NAIS/Aromat	\$2.21	650	375	829	272	31
8	Sig Tail Kapton Ckt	1.10	SIGTAIL2.MAX	Channel	\$30.00	0	0	0	3	0
9	Sig Tail Kapton Ckt	1.12	SIGTAIL3.MAX	Cirexx	\$21.25	528	500	10625	30	30
10	Sig Tail Kapton Ckt	2.00	SIGTAIL4.MAX	Cirexx	\$35.00	138	0	0	0	0

NOTES: 1. Signal tail setup cost \$200, testing \$450 for first batch.

New Order TOTAL= \$20,273

- 2. HV tail setup cost \$ tbd
- 3. SS Modules= 3250 ea
- 4. DSp-u Modules= 575 ea
- 5. DSp-d Modules=575 ea
- 6. DSs-u Modules=575 ea
- 7. DSs-d Modules=575 ea
- 8. Based on 12% of modules due to reuse at rod loading

Module Count
3250
575
575
575
575
575

Tailparts.xls

HTV3.00 Prod.

tbd

0
0
30
31
31
0
0
0
0
0