



LV Power Supply Options(ARC)



- ARC needs +5V/3.5A and -5V/0.5A
- Agilent E3631A
 - +6V/5A, +25/1A, -25V/1A
 - Built-in volt/current meters, Over-voltage and Over-Current Tripping
 - ~\$1122 each (Need 2)
- Lambda JWS50-5/A
 - 5V/10A
 - No volt/current meters, Over-current Tripping Below 10A
 - ~\$120 each (Need 4)