

Revised: 3/23/2004

ITEM	Quantity	Description	Part No.	Mfg	Dist	Dist PN	Spec	Cost ea	Total Cost	Sum
1	4	RS232 8 Relay Bd	P85PRO	NCD	NCD	P85PRO		139	556	556
2	1	RS232 Quick kit	OS12	NCD	NCD	OS12		19	19	575
3	1	Power Supply 12v	MK40S-12	AstroDyne	-	-	12v@3.5A	40	40	615
4	1	Rack mount chassis	CH14401	Bud	Newark	95F948	1.75x17x8	45	45	660
5	1	Rack mount panel	PA1102GA	Bud	Newark	91F390	3.5x19	16.8	16.8	676.8
6	8	SHV Bulkhead Connector, jack	51494-1	Amp	Newark	89F3394	1.875"	15	120	796.8
7	1	Triax bulkhead connector	7978-TRX-TBC	Keithley	Keithley	7978-TRX-TBC		50.4	50.4	847.2
8	1	Triax Cable	1078-TRX-3	Keithley	Keithley	1078-TRX-3	0.9 M	122.3	122.3	969.5
9	1	Serial cable	SER	NCD	NCD	SER	6ft	6	6	975.5
10	1	HV Connector					15PF		0	975.5
11	1	Misc assembly parts, wiring etc						150	150	1125.5
12	1	USB/HPIB Interface	NI GPIB-USB-B	National Ins.	-	778416-01	on cable	495	495	1620.5
									0	1620.5
									0	1620.5

TOTAL

	Hrs	Rate	Cost	Total Cost
Labor Costs:				
Chassis Assembly	2	60	60	140
Panel Machine work	1	40	120	260
Wiring	3	40	160	420
Test	4	40	240	660
Software setup	6			
		TOTAL		1560
	16			